

Download Minnkota Terrova Owners Manual

Props and shafts are not 100% symmetrical. Often times simply removing the prop, rotation it 180 degrees, and re-installing it will lessen or eliminate the incidence of vibration.98 Ranger 518SVS 00 200 Merc: Manual jackplate, HDS12, HDS9, MK Fortrex. Cparsons10 - AR: 18 Ranger RT198P 19 150 MercTo have your STRATOS added to this list, click on Add a Boat fill in the form and hit "Submit". Your boat will be added asap. * To add a photo(s) to your listing, e-mail me a .jpg file.8/9/2018 I've had my 240LTS for 2 months now and I can say that this is hands down the baddest boat that I've ever owned. Its an incredibly dry ride and a great handling boat and paired with the Minn Kota Ulterra, it's quite maneuverable for a large boat. The jump seats in the back and the Yeti with the cushion seat mean I can also take my wife and boys out, something I couldn't do in my ...